

VOLUME III

PHASE I

DOCUMENTARY AERIAL DAM SAFETY INSPECTION **PHOTOGRAPHS** **LAKE LURE DAM AND APPURTENANCES**

North Carolina ID No. RUTHE-003
Federal ID No. NC – 100
Project No. ME-16-006


Prepared For:

TOWN OF LAKE LURE
Post Office Box 255
2948 Memorial Highway (US Highway 64/NC Highway 9)
Lake Lure, Rutherford County, North Carolina 28746
(828) 625-9396 – Telephone
(828) 625-9983 – Telephone
(828) 625-8371 - Facsimile
Attention: Mr. Ron Nally, Town Manager
<townmgr@townoflakelure.com>


Prepared By:

Marks Enterprises of NC, PLLC
1 Palatka Street
Arden, North Carolina 28704
Attention: Dr. B. Dan Marks, Ph.D., P.E., Principal
(828) 231-0598
drbdan@bellsouth.net

September 1, 2017




Spillway Wall




Aerial View of Spillway Wall at 250'



Aerial of Spillway Wall at 200'



Aerial Spillway View



Tainter Gate #1



Tainter Gate #2
Leaks and Vegetation are visible



Tainter Gate #3 and Trash Gate
Leaks and Vegetation are visible



Trash Gate



Center Of Arch Upper View. Bay #4



Left Side Of Buttress Upper View. Bay #4

Right Side Of Buttress lower View. Bay #4






Right Side Of Buttress Upper View. Bay #4

Under Bridge View. Bay #4






Bay #6 Upper View



Center Of Arch Ground View. Bay #5




Center Of Arch Upper View Leakage Coming From Arch Section. Bay #5



Center Of Arch Upper View. Bay #5



Constant Rain Of Lake Water Due To Leakage Above From Arch Section. Bay #5



Left Side Lower Arch. Bay #5



Left Side Upper Arch View. Bay #5



Mid Section Of Arch. Bay #5



Right Side Lower Arch View. Bay #5



Right Side Lower Rear Buttress View. Bay #5



Right Side Of Buttress lower View. Bay #5



Right Side Of Buttress Upper View. Bay #5

Sewer Pipe. Bay #5





Sewer System Access. Bay #5

