




Bay #6 Center Arch View

© Andrew Konopka











Bay #7 Arch View



Bay #7 Back Wall of Power House








Bay #7 Behind Power House, Large Leak





Bay #7 Behind Power House, Leakage Visible




A close-up photograph of a large leak, showing a thick, dark, reddish-brown sediment or iron oxide coming through. The sediment is highly textured, with many small, bright, reflective spots that give it a glistening appearance. The overall color is a deep, mottled brown with some darker, almost black, streaks and patches. The texture is uneven and granular.

Bay #7 Behind Power Houes. Close up of Large Leak shows Iron Oxide/Sediment coming through from Lake above




Lower Outside Back Wall Of Power Houses. Bay #7






Rear Of Back Wall Of Power House. Bay #7











Center Of Arch Ground View. Bay #8





Left Side Of Buttress Lower View. Bay #8



Left Side Under Bridge. Bay #8








Right Side Of Buttress Lower View. Bay #8





Right Side Of Buttress. Bay #8



Right Side Under Bridge. Bay #8








Storage Behind Shed. Bay #8










Center Of Arch Ground View. Bay #9





Center Of Arch Lower View. Bay #9






Center Of Arch Upper View. Bay #9






Left Side Of Arch Leakage Coming From Arch Form Section. Bay #9





Left Side Of Arch. Bay #9






Left Side of Buttress. Bay #9





Right Side Of Arch Leakage Coming From Arch Form Section. Bay #9





Right Side Of Arch Lower View. Bay #9






Right Side Of Arch Upper View. Bay #9





Right Side Of Buttress Lower View. Bay #9





Right Side Of Buttress. Bay #9





Buttress Between Bays 9 and 10



