



Front Of Power House. Bay #7



Overview of power House Porch


© Andrew Konopka



Water coming out from under Staircase, Due to Water Leaks in Bays 8 and 9



Constant Water Flow coming from under Staircase, Depth 2.5"



Power House Roof



Power House Roof



Front Wall Of Power House



Front Of Celing In Power




Power House Office



Back Wall Of Power House



Rear Of Ceiling In Power House



Larger Generator




Smaller Generator



Stairs Leading To Turbine Room From Main Level In Power House



Facing Rear Of Turbine Room (UpStream)




Larger Turbine



Smaller Turbine


Top Of Penstock (Facing Downstream)



545
294
548
351
596
292
292

471 -
519 -
490 -
529 -
442 -

372
371
318
331
254-249
223
455
489
370
385
285





Penstock Branch To Would Be Future Third Turbine




Penstock for Optional Third Turbine

Third Turbine Pit







Bay #6 Unused Water Exhaust Output for Optional Third Turbine



Aerial Overview of The Dam at Lake Lure



Aerial View Front Side of Dam



Dam Aerial Overview

