



February 14, 2011

Addendum 1

RFQ-11-32

The Request For Quotation – Repair or Replace 40 HP Inverter Motor is hereby clarification of the following:

1. On Specifications Page 2, under section 1.02 A, add the following:

Existing motor RPM is 1180.

Existing motor manufacturer is TECO/Westinghouse.

All other terms and conditions remain the same.

Sincerely,

CITY OF WINTER HAVEN

A handwritten signature in cursive script that reads 'Bob Bishop'.

Bob Bishop

Procurement Services Division Director