

		Bidder No 1	Bidder No 2	Bidder No 3	Bidder No 4
		TMI Coatings, Inc. St Paul, MN	Caldwell Tanks, Inc. Louisville, KY	H2O Towers, LLC Saline, MI	Classic Protective Coatings Menomonie, WI
ITEM	DESCRIPTION	Lump Sum	Lump Sum	Lump Sum	Lump Sum
A	Repairs to interior and spot repairs of paint coating of exterior structure, removal of complete interior existing coatings and complete painting interior of elevated water storage tank Completion Time	\$127,300.00 Within 60 days	\$106,500.00 Within 60 days	\$84,000.00 Within 6 weeks	\$123,500.00 Within 45 days
B	Repairs to interior, spot repair interior and existing coatings of elevated water storage tank Completion Time	\$73,000.00 Within 40 days	\$79,880.00 Within 45 days	\$15,000.00 Within 8 days	\$76,400.00 Within 30 days
C	Design, fabricate and install modifications to the balcony hand rail system Completion Time	\$20,200.00 Within 20 days	\$23,800.00 Within 21 days	\$3,350.00 Within 4 days	\$17,000.00 Within 14 days
		Bidder No 5	Bidder No 6	Bidder No 7	Bidder No 8
		Tank Rehab.com, Inc. Pointe Vedra Beach, FL	Pittsburg Tank & Tower Maint. Henderson, KY	Utility Service Co., Inc. Perry, GA	Worth Contracting, Inc. Jacksonville, FL
ITEM	DESCRIPTION	Lump Sum	Lump Sum	Lump Sum	Lump Sum
A	Repairs to interior and spot repairs of paint coating of exterior structure, removal of complete interior existing coatings and complete painting interior of elevated water storage tank Completion Time	\$78,000.00 Within 45 days	\$68,320.00 Within 6 weeks	\$86,100.00 Within 45 days	\$83,200.00 Within 45 days
B	Repairs to interior, spot repair interior and existing coatings of elevated water storage tank Completion Time	\$38,000.00 Within 30 days	\$29,600.00 Within 2 weeks	\$62,700.00 Within 30 days	\$57,119.00 Within 40 days
C	Design, fabricate and install modifications to the balcony hand rail system Completion Time	\$8,500.00 Within 30 days	\$9,500.00 Within 1 week	\$8,000.00 Within 7 days	\$3,000.00 Within 0 days

