


Below is a photo which shows the on the East side of home.




[www.HCAuditor.org](http://www.HCAuditor.org)  
6000080036200 10/20/2008

As the fence has rapidly deteriorated our family has removed portions of the fence for safety purposes. Below are pictures of the current fence.



additional photo of the west side



Eastern side of fence



Placement of fence on West side.